



Straight female connector. copper x BSP parallel female thread.

GENERAL INFORMATION

Size	Pattern No.	Box Qty	Code	Barcode	Price (£) ex VAT
8mm x 1/4"	YP2	5	08087	5022050080875	£9.98
15mm x 1/2"	YP2	10	08090	5022050080905	£7.05
22mm x 3/4"	YP2	10	08092	5022050080929	£10.20
28mm x 1"	YP2	5	08093	5022050080936	£19.28
35mm x 1 1/4"	YP2	1	08094	5022050080943	£34.58
42mm x 1 1/2"	YP2	1	08095	5022050080950	£44.88
54mm x 2"	YP2	1	08096	5022050080967	£71.16

DIMENSIONS (mm)

Code	Description	a	Za	S
08087	8mm x 1/4" YP2	25	16	19
08090	15mm x 1/2" YP2	38	20	26
08092	22mm x 3/4" YP2	38	20	31
08093	28mm x 1" YP2	48	26	39
08094	35mm x 1 1/4" YP2	56	29	48
08095	42mm x 1 1/2" YP2	60	29	55
08096	54mm x 2" YP2	70	33	66

PRESSURE & TEMPERATURE

YORKSHIRE POTABLE PERFORMANCE WHEN CORRECTLY ASSEMBLED WITH COPPER TUBE TO BS EN 1057

Service temperature

Size	-40° C (Min)	30° C	65° C	110° C (Max)
6mm to 54mm	16 bar	16 bar	10 bar	6 bar
67mm	10 bar	10 bar	6 bar	4 bar

GUARANTEE

Pegler Yorkshire 25 Year Guarantee - Terms and Conditions

Products are subject to a 25 year guarantee that is between Pegler Yorkshire and the final purchaser of the product.

The guarantee is subject to proof of purchase being supplied.

This guarantee does not affect any statutory rights the consumer may have in law.

The guarantee covers manufacturing or material defects when installed in accordance with our instructions on specified tube materials and applications, and does not cover parts subject to normal wear and tear.

This product range has been designed for the use of homeowners, domestic and commercial applications and therefore the Guarantee is subject to the product being properly selected for their intended service conditions.

The guarantee is not applicable where the product is fitted contrary to the conditions in the fitting instructions.

This is reinforced where valves are covered by the European Pressure Equipment Directive (PED97/23/EC) where Installation, Operating and Maintenance Instructions are supplied with each product and/or carton.

Provided it is installed correctly and receives adequate preventative maintenance it should give years of trouble-free service.

Abusive behaviour and accidental damage to the product are not covered by this guarantee.

The extent of this liability is limited to the cost of the replacement of the defective item and not to installation or consequential damages.

APPROVALS



[BSI](http://www.bsi.com)



[WRAS](http://www.wras.co.uk)